
throws the work against the stop C, by means of plungers D and E.

In profiling or face milling fixtures, clamps on top of the work often interfere with the cutter. Fig. 16 illustrates a method of



Machinery

Fig. 14. An Equalized
Cla
mpi
ng
Arr
ang
eme
nt
ma
kin
g
use
of a
Han
dwh

holding this class of work by means of a flange at the bottom. Clamp A is operated by the wing-nut B and floats in slots to allow for any

casting variation, and for hooking the projection on the clamp over the flange. The piece C is thrown over after